

# **SAS2.0 Linux OS Driver Release Notes**

**Driver Version: mpt2sasbtm-14.00.00.00-1**

**06/29/2012**

## **Compatibility:**

- SAS 2004, 2008, 2008\_1, 2008\_2, 2008\_3, 2116\_1, 2116\_2, 2208\_1, 2208\_2, 2208\_3, 2208\_4, 2208\_5, 2208\_6, 2308\_1, 2308\_2 and 2308\_3.

## **Special Notes For This Build:**

- This Build supports only RHEL4.6, RHEL4.7, RHEL4.8 and SLES9 SP4 Operating Systems only.
- This build includes binaries for X86, X86\_64 and PPC64 architectures only.
- The diskdump will not work if the controller is in a non-operational state.
- There is a problem in the fixid kit based DUD which prevents using it for DUD based installation.

## Current Errata

- None

## Driver Release Package Contents

### • *Source tarball*

Source tarball is named as: mpt2sasbtm-<version>-src.tar.gz

where:

<version> = version tag for this rpm

### • *RPM Binaries:*

RPM images are named as: mpt2sasbtm-<version>-<release>-<os>.<arch>.rpm

where:

<version> = version tag for this rpm

<release> = release tag for this rpm

<os> = {rhel4}

<arch> = x86\_64 – Opteron Processor, w/ x86\_64 install  
i686 – i686 or later processor (Red Hat)

### • *Driver Update Disks*

dud images are named : mpt2sasbtm-<version>-<release>-<os>.<arch>.dd.gz

where:

<version> = version tag for this rpm

<release> = release tag for this rpm

<os> = {rhel4}

<arch>        =        x86\_64 – Opteron Processor, w/ x86\_64 install  
                      i686 – i686 or later processor (Red Hat)

• *DKMS*

DKMS tarball is named : mptlinux-<version>-<release>.dkms.tar.gz

where:

<version>    =        version tag for this rpm  
<release>    =        release tag for this rpm

This is an rpm that provide prebuilt binaries for RHEL4.7 release, and will compile drivers on the fly for the other kernels. Here is help on dkms:  
<http://linux.dell.com/dkms/dkms.html>

• *SRPMS*

SRPM images are named mptlinux-<version>-<release>.src.rpm

where:

<version>    =        version tag for this rpm  
<release>    =        release tag for this rpm

SuSE:

i586	SLES9	SP4 (2.6.5-7.308)	(bigsmpt, debug, default, smpt)
x86_64	SLES9	SP4 (2.6.5-7.308)	(default, smpt)
ppc	SLES9	SP4 (2.6.5-7.308)	(pseries64)
ia64	Not supported in this release		

Red Hat:

i686	RHEL4	Update 6 (2.6.9-67.EL)	(normal, hugemem, smpt)
		Update 7 (2.6.9-78.EL)	(normal, hugemem, smpt)
		Update 8 (2.6.9-89.EL)	(normal, hugemem, smpt)
x86_64	RHEL4	Update 6 (2.6.9-67.EL)	(normal, largesmp, smpt)
		Update 7 (2.6.9-78.EL)	(normal, largesmp, smpt)
		Update 8 (2.6.9-89.EL)	(normal, largesmp, smpt)
ppc	RHEL4	Update 6 (2.6.9-67.EL)	(normal, largesmp)
		Update 7 (2.6.9-78.EL)	(normal, largesmp)
		Update 8 (2.6.9-89.EL)	(normal, largesmp)
ia64	Not supported in this release		

## **Major Changes For Version 14.00.00.00-1**

**Release Date:** 06/29/2012

### **General Changes**

- CQ 300005: Bump driver version for phase 14 GCA release

## **Major Changes For Version 13.254.02.00-1**

**Release Date:** 05/30/2012

### **General Changes**

- CQ 289489: Bump driver version for phase 14 beta release

### **Defect fixes**

- CSET CQ282260: Providing a negative value to sdev\_queue\_depth parameter leads to incorrect queue depth for a SAS drive. When the driver is loaded by providing a negative value for the SAS queue depth (sdev\_queue\_depth) parameter, then the qdepth value for the SAS devices is incorrect. Fix is to cast the unsigned integer variable sdev\_queue\_depth to an integer before comparing it with a negative value.
- CSET CQ 286976: If the requested IOCTL block state is equal to NON\_BLOCKING and mutex\_trylock is succeed, then control flow goes to mutex\_lock\_interruptible() which will deadlock. To fix this, code in \_ctl\_ioctl\_main is rearranged so the success of mutex\_trylock is not calling mutex\_lock\_interruptible().
- CSET CQ 286984: Infinite TUR command retries happen when a bad drive is connected. When a drive that continuously sends Check Condition status, with SenseKey/ASC/ASCQ as 0x02/0x04/0x00 (indicating that the device is not ready) is connected, then it is observed that the driver continuously sends TUR commands to the drive, without ever signalling an error. The return code of the function which issues the TUR command was not being checked

properly for number of retries. Modified this code to correctly check the return code and indicate an error if the number of retries is exhausted.

## **Major Changes For Version 13.254.01.00-1**

**Release Date:** 04/02/2012

### **General Changes**

- CQ255068: The customer branding string for the "SSD 910 Series" controller was updated.
- CQ255069: The copyright string in all the driver sources was changed to 2012.
- CQ264671: Bump driver version to 13.254.01.00 for phase 14 pre alpha release
- CQ264678: MPI 2.0 Release: MPI 2.0 Rev V (2.0.14) specification and 2.00.25 header files

### **Defect fixes**

- CQ252479: Target IDs of the removed drives are taken by the existing drives/enclosure in the topology. Following host reset, firmware discovery is reassigning another hard drive in the topology to the same device handle as the device that is getting hot removed. When the driver device removal routine is called, there will be two hard drives with the matching device handle in the internal device link list. In the device removal routine, we call a separate function which is removing the device. Since this routine is having the device handle passed in as input parameter, the routine will be traversing the internal device link list searching for matching device handle. Since there will be two devices with matching device handle, an incorrect device could be removed. To fix this issue, the device is removed in the device removal routine, instead of calling the function that removes the drive based on the handle.

- CSET CQ259044: Driver oops associated with the max\_queue\_depth command line option set too small. The driver change is to set the scsi mid layer can\_queue value equal to the max\_queue\_depth. Then the overall message frames required IO is the minimum of either (max\_queue\_depth plus internal commands) or the IOC global credits.
- CSET CQ259281: The log\_info constant is supposed to be IOP\_LOGININFO\_CODE\_TASK\_TERMINATED rather than the non-sensical 0x1CA86D0. Changed 30050000 to 0x30050000 in \_base\_sas\_log\_info.
- CSET CQ262005: Turning on the command line option initialize\_target\_mode is resulting in driver panic under 32 bit Linux OS. The panic is due to a reference to ioc->pfacts when its set to NULL. Normally ioc->pfacts is set to valid pointer, however in this case it was set to NULL. It got set to NULL when the diag reset was issued as part of the initialize\_target\_mode handling. The reason it was set to zero is due to a bug in \_base\_get\_ioc\_facts. From \_base\_get\_ioc\_facts we are refreshing the IOC FACTs data. In that code before we refresh this structure, we are initializing the structure to zero. When it is getting initialized to zero, the size passed into the memset call was too large. The size was set to 64 bytes, when it should of been 60 bytes. This resulted in the parameter ioc->pfacts getting clear.

## **Major Changes For Version 13.00.00.00-1**

**Release Date:** 02/17/2012

### **General Changes**

- CQ 252247: Update version number to 13.00.00.00-1 to indicate this driver as a Phase-13 GCA release driver

### **Defect fixes**

- None.

## **Major Changes For Version 12.254.03.00-1**

**Release Date:** 02/15/2012

### **General Changes**

- None.

### **Defect fixes**

- CSET CQ251542 (CQ251237): A hard drive is being OFFLINED when there is a hard reset issued in combination with hot removing another hard drive. Following host reset, firmware discovery that is reassigning another hard drive in the topology to the same device handle as the device that is getting hot removed. Until the driver device removal routine is called, there will be two hard drives with the matching device handle in the internal device link list. In the device removal routine, we call a separate function which is moving the device from BLOCKED into OFFLINE state. Since this routine is having the device handle passed in as input parameter, the routine will be traversing the internal device link list searching for matching device handle. Since there will be two devices with matching device handle, there will be both devices getting OFFLINED. To fix this issue, we should be the sas address as input instead of device handle.

## **Major Changes For Version 12.254.02.00-1**

**Release Date:** 12/08/2011

### **General Changes**

- CQ234984: Update version number to 12.254.02.00-1.

### **Defect fixes**

- None.

## **Major Changes For Version 12.254.01.00-1**

**Release Date:** 11/28/2011



## **General Changes**

- CQ231021: bump driver version
- CSET 230227 (CQ 230140): MPI2 Update Rev U (2.0.23)
- CSET 228119 (CQ 220045): Fix security scan issues reported by source code analysis tool. Modified the source code as per the findings reported by the source code analysis tool. None of the driver functionalities has changed. Source code for the following functionalities has been touched:
  - SMP Passthrough IOCTL
  - Debug messages for MPT Replies
  - Task Management using sysfs
  - Disk removal
  - Trace Buffer
- CSET 228120 (CQ 208765): Improvement were made to better protect the sas\_device, raid\_device, and expander\_device links. There were possible race conditions surrounding reading an object from the link list while from another context in the driver it was removing it. The nature of this enhancement is to rearrange locking so the link lists are better protected.
- CSET 228117 (CQ 220601): Add support for in the IOCTL path for opcode MPT2COMMAND. For SATA\_PASSTHROUGH commands that end with time outs, the driver will issue a target reset instead of host reset.
- CSET 228118 (CQ 213206): Driver is snooping on completions for the 0x31110630 loginfo. After the scsi mid layer sent the same command with four retries and same loginfo, the driver will return DID\_NO\_CONNECT instead of DID\_SOFT\_ERROR, and will and offline the device. This will prevent any further request from the filesystem layer.

## **Defect fixes**

- CSET 230301 (CQ 230280): An inactive volume that is activated is not seen immediately by the OS: The events that are sent by controller firmware to driver have changed for when an inactive volume is activated. In previous firmware releases, the driver would have received a MPI2\_EVENT\_IR\_CHANGE\_RC\_UNHIDE event when a volume was activated, whereas now its receiving MPI2\_EVENT\_IR\_CHANGE\_RC\_REMOVED. Due to this change, the driver now is sending a target reset to the volume at the same time the Volume is getting detected by the OS. The OS is sending an INQUIRY, and its getting aborted by the background target reset, which results in the volume never getting reported. To resolve this issue, the driver is not needing to send the target reset to the volume when its MPI2\_EVENT\_IR\_CHANGE\_FLAGS\_FOREIGN\_CONFIG.

## **Major Changes For Version 12.00.00.00-1**

**Release Date:** 11/08/2011

**General Changes**

- CQ 228662: Update version number to 12.00.00.00-1 to indicate this driver as a Phase-12 GCA release driver.

**Defect fixes**

- None.

**Major Changes For Version 11.254.01.00-1**

**Release Date:** 08/30/2011

**General Changes**

- CQ 208433: Correctly identify the customer boards and display branding string in the message logs.
- CQ 209775: Add support for SATA Initialization Timeout:  
When the driver sends internal TUR to check the state of the hotplugged device if the command is returned with non zero IOC status then the command is retried until the retry count is exhausted. To handle the drives which are in SATA Initialization failure state the driver checks the loginfo for 0x31111000 (which is SATA Initialization Timeout code) and if so, the driver retry the TUR once (instead of retry count times) to check if the device is ready after the target reset initiated by the firmware, and if the driver receives the same 0x31111000, it gives up adding the device.
- CSET 217005 (CQ 217001): Add MPI2 Rev R (2.0.12) header files (for Phase 12.0).
- CQ 218153: Change driver version to 11.254.01.00 for phase 12 pre alpha release.

**Defect fixes**

- None.

## **Major Changes For Version 11.00.00.00-1**

**Release Date:** 08/23/2011

### **General Changes**

- CQ 215693:- Update version number to 11.00.00.00-1 to indicate this driver as a Phase-11 GCA release driver.

### **Defect fixes**

- None.

## **Major Changes For Version 10.254.02.00-1**

**Release Date:** 08/17/2011

### **General Changes**

- None.

### **Defect fixes**

- CSET 213015(CQ 208648): IOCTL request are taking a long time to complete back from device driver. It appears the application has hung: There is a race in the driver where the a response is getting returned by the firmware between the time the request was sent to firmware, and before the driver had time to go to sleep to wait for the response. When this happens, the driver is never woken up until the timeout has elapsed. This defect is occurring because the driver is initializing the completion queue in between sending the request and going to sleep. To solve the issue, the driver should initialize the completion queue prior to sending the request to firmware.

.

## **Major Changes For Version 10.254.01.00-2**

**Release Date:** 07/06/2011

### **General Changes**

- None.

### **Defect fixes**

- CQ 204696:- Booting to SLES 9 SP4 after DUD installation is getting failed - This was regression of CQ 166870. As part of that the script files in the source code are appended with .sh name, so the clean script is renamed from clean to clean.sh. But the DUD creation script for SLES9 (make\_dud) is not updated to call clean.sh instead of clean. This caused linking on .o files compiled for default kernel to create .ko file for smp kernel and hence resulted in corrupted memory mapped module, which on load resulted in panic.

### **Major Changes For Version 10.254.01.00-1**

**Release Date:** 06/06/2011

### **General Changes**

- CQ 199890:- Adding branding support to identify customer specific adapter.

### **Defect fixes**

- CSET 200702(CQ 187701): Port Reset is taking long time(around 5 mins) to complete while issued during creating a volume : Add error checking in slave\_configure to check for configuration pages failing, and return "1" so the device is not configured. The config pages are failing if raid volume is configured while issuing a host reset, thus driver is reading stale data and proceeding to attempt to add. The fix is to return error so the volume is not configured. It is okay if the driver returns with error from slave\_configure because from the post reset handling, the driver is scanning for new volumes, and the volume is eventually added.

### **Major Changes For Version 10.00.00.00-1**

**Release Date:** 05/11/2011

### **General Changes**

- CQ 194609:- Update version number to 10.00.00.00-1 to indicate this driver as a Phase-10 GCA release driver.

### **Defect fixes**

- None.

## **Major Changes For Version 09.254.02.00-1**

**Release Date: 04/26/2011**

### **General Changes**

- None.

### **Defect fixes**

- CSET 192375(CQ 188953) – Reduce cache misses in command submission path: In a high-IOPS workload, mpt2sas\_base\_get\_smid\_scsiio shows up in the top 20 cache misses. This is because the data structure used for allocating SMIDs is cache unfriendly; freed SMIDs are placed on the tail of the list, guaranteeing a cache miss by the time we allocate it again. By placing the freed SMID at the head of the list, we increase the likelihood of it being cache-hot when it's used again.
- CSET 192374(CQ 188951) – Prevent heap overflows and unchecked reads: At two points in handling device IOCTL's via /dev/mpt2ctl, user supplied length values are used to copy data from user space into heap buffers without bounds checking, allowing controllable heap corruption and subsequently privilege escalation. Additionally, user supplied values are used to determine the size of a copy\_to\_user() as well as the offset into the buffer to be read, with no bounds checking, allowing users to read arbitrary kernel memory.
- CSET 192370(CQ 178865) - Running the load\_diag\_trace\_on.sh and diag\_rest with 30 secs delay make the driver to crash after some time: The issue surrounds the load\_diag\_trace\_on.sh driver sending a request to the driver while a diag reset is active. If this occurs before ioc is initialized, the message queues will not be setup, thus resulting in a 1550 fault. To fix the problem: (1) We have moved the "ioc\_reset\_count" counter so its incremented after the host reset has completed bringing up the controller. This will prevent the script from sending the request too early. (2) We have added a sanity check in the Sysfs so the script will not be allowed to send a request to driver while driver is busy with recovery. (3) All the diag buffer code will be changed to use a unique message

frame callback index. The previous implementation was having diag buffer code share the same callback index with IOCTLs. So if there was a timeout with IOCTLs, it would not be possible to send a RELEASE prior to diag reset because IOCTLs owned the callback index due to the timeout. With this change, this will insure the RELEASE will be sent.

- CSET 186524(CQ 184414) - Hang when there is smart error on IBM platform: Driver was sending a SEP request during interrupt context which required sleeping. The fix is to rearrange the code so a fake event MPT2SAS\_TURN\_ON\_FAULT\_LED is fired from interrupt context, then later during the kernel worker threads processing, the SEP request is issued to firmware.
- CSET 186520(CQ 184402) - Power PC - first request sent through message queues is timing out: We have to revert to sending two separate 32bit pci writes, accompanied with spin locks.
- CSET 186518(CQ 184822) - Update MPI2 headers files for fix bug in IO Unit Page 10.

## **Major Changes For Version 09.254.01.00-1**

**Release Date:** 03/07/2011

### **General Changes**

- CQ 180565 – MPI2 Rev R (2.0.10) and v2.00.19 header files (for Phase 10.0) are added.
- CSET 182617(CQ 181789) - Add support for Customer specific Identification: Report branding messages when device driver loads, based on specific customer subsystem vendor and device Ids.

### **Defect fixes**

- None.

## **Major Changes For Version 09.00.00.00-1**

**Release Date:** 02/21/2011

### **General Changes**

- CQ 179053:- Update version number to 09.00.00.00-1 to indicate this driver as a Phase-9 GCA release driver.

### **Defect fixes**

- None.

## **Major Changes For Version 08.254.04.00-1**

**Release Date:** 02/11/2011

### **General Changes**

- CQ 177330:- Adding support for displaying customer branding information for the Mustang controller.

### **Defect fixes**

- None.

## **Major Changes For Version 08.254.03.00-1**

**Release Date:** 01/18/2011

### **General Changes**

- None.

### **Defect fixes**

- CQ 171768:- RHEL4 Driver Update Disks are not recognizing the Thunderbolt and Mustang controller. To fix this corresponding PCI IDs are added in driver update disk configuration files.
- CQ 171754:- The shutdown/reboot is not completed and stuck in driver shutdown handler: The change done in CQ 166865 is causing this and it is due to some lock contention in calling the scsi\_remove\_host from the shutdown handler. The scsi\_remove\_device also blocked. The shutdown handler is modified so that it will neither remove host nor remove devices.

## **Major Changes For Version 08.254.02.00-1**

**Release Date:** 11/22/2010

## **General Changes**

- CQ 166875:-Adding support to retrieve firmware diagnostic trace buffers between every diagnostic reset (and FAULTs): The current problem we face is the ring buffer or trace buffer is only good since the last host reset. This enhancement handle test cases involving multiple diag resets, where firmware engineers are asking for trace buffer between each host reset. Additional changes in the driver are as follows: (1) inhibit incrementing the ioc->ioc\_reset\_count counter when the driver is unloading (2) change the ioc->diag\_buffer\_status to MPT2\_DIAG\_BUFFER\_IS\_RELEASED for the case when there is a FAULT (3) change the ioc->ioc\_reset\_count SysFS attribute from "%08d" to "%d", as the script was failing after 8 iterations of resets. (4) change the pulling of the trace buffer size from 4096 to 4095 (because hit was hitting an warning in the kernel)
- CQ 166865:- Block I/O when system shutdown is in process. System panics when rebooting in a multi-pathing configuration. The root cause is due to the multi-pathing driver is sending additional request to the driver after the PCI shutdown notifier is called. From the shutdown routine, the driver is freeing all the memory associated to sending IO request, so if there additional IO request arriving after this point, the host will panic. To solve this issue, the driver needs to remove the devices from the OS prior to freeing its memory.
- CQ 166026:- Phase 9 revision Q header update
- CQ 160686:- Set Max Sector Count of SAS2 MPT Linux Driver: Request is to have the capability to override the default max\_sectors setting at load time, taking max\_sectors as an command line option when loading the driver. The setting is currently hard-coded in the driver to 8192 sectors (4MB transfers). If max\_sectors is specified at load time, minimum specified setting will be 64, and the maximum is 8192. The driver will modify the setting to be on even boundary. If max\_sectors is not specified, the driver will default to 8192.

## **Defect fixes**

- CSET 166867(CQ 156055):- Big Endian issue on 32bit PPC: (1) removed the BITS\_PER\_LONG in \_base\_send\_ioc\_init as this code was failing to compile on 32bit PPC. This code was replaced by using the cpu\_to\_le64 API and u64 typecasting for the 32 bit fields. (2) Fixed all the BIG ENDIAN issues by installing sparse, and compiling with the C=2 CF="-D\_\_CHECK\_ENDIAN\_\_" option.

## **Major Changes For Version 08.00.00.00-1**



**Release Date:** 10/29/2010

**General Changes**

- CQ 148653:- Update version number to 08.00.00.00-1 to indicate this driver as a Phase-8 GCA release driver.

**Defect fixes**

- None.

**Major Changes For Version 07.254.08.00-1**

**Release Date:** 10/26/2010

**General Changes**

- None.

**Defect fixes**

- CQ 161421 - Removal of driver & adding the driver multiple times on RHEL 4.8 OS causing kernel panic.: The driver was releasing the reference count of the scsi\_host structure and then trying to access ioc which is actually private data of the scsi\_host structure and hence resulting in panic. This is fixed by moving the release of reference count to the end of the remove handler.

**Major Changes For Version 07.254.07.00-1**

**Release Date:** 10/01/2010

**General Changes**

- CSET 158279(CQ 155831) - Add support for Customer specific Identification: Report branding messages when device driver loads, based on specific customer subsystem vendor and device Ids.

## **Defect fixes**

- CSET 158283(CQ 152497) - Kernel Panic during Large Topology discovery: There was a configuration page timing out during the initial port enable at driver load time. The port enable would fail, and this would result in the driver unloading itself, meanwhile the driver was accessing freed memory in another context resulting in the panic. The fix is to prevent access to freed memory once the driver had issued the diag reset which woke up the sleeping port enable process. The routine `_base_reset_handler` was reorganized so the last sleeping process woken up was the `port_enable`.
- CSET 158281(CQ 144099) - False timeout after hard resets: There were two issues which lead to timeout. (1) Panic because of invalid memory access in the broadcast asyn event processing routine due to a race between accessing the scsi command pointer from broadcast asyn event processing thread and completing the same scsi command from the interrupt context. (2) Broadcast asyn event notifications are not handled due to events ignored while the broadcast asyn event is activity being processed from the event process kernel thread. In addition, changed the `ABRT_TASK_SET` to `ABORT_TASK` in the broadcast async event processing routine. This is less disruptive to other request that generate Broadcast Asyn Primitives besides target reset; those for example are clear reservations, microcode download, and mode select.

## **Major Changes For Version 07.254.05.00-1**

**Release Date:** 08/23/2010

## **General Changes**

- CQ 151553 - Revision P header update: (a) Added enable/disable SATA NCQ operations to SAS IO Unit Control Request. (b) Modified Host Based Discovery Action Request message format. (c) Removed Device Path bit from IO Unit Page 1 Flags field. (d) Added description of ChainOffset field for Diagnostic Data Upload Tool. Chaining is not allowed.

## **Defect fixes**

- CSET 151561(CQ 148348) - Increasing `max_queue_depth` in Linux Driver not honored above 30,000 - Bug fix in the queue depth calculation when queue depth exceeded the `MaxReplyDescriptorPostQueueDepth`. The algorithm was resizing the queues incorrectly, that is fixed in the driver.

- CSET 151560(CQ 147145) - the "internal device reset complete" event is not supported for older firmware prior to MPI Rev K (which is Phase 3) - We added a check in the driver so the "internal device reset" event is ignored for older firmware. When ignored, the tm\_busy flag doesn't get set nor cleared. Without this fix, IO queues would be frozen indefinitely after the "internal device reset" event, as the "complete" event never sent to clear the flag.
- CSET 151556(CQ 141553) - When zoning end devices, the driver is not sending device removal handshake algorithm to firmware. This result in controller firmware not sending sas\_topology\_add events when the device is added next time. The current design is avoiding the handshake when the VACANT bit is set in the PHY status. The fix is the driver should be doing the device removal handshake even though the PHYSTATUS\_VACANT bit is set in the PhyStatus of the event data.

## **Major Changes For Version 07.00.00.00-1**

**Release Date: 07/30/2010**

### **General Changes**

- CQ 148653:- Update version number to 07.00.00.00-1 to indicate this driver as a Phase-7 GCA release driver.

### **Defect fixes**

- None

## **Major Changes For Version 07.254.03.00-1**

**Release Date: 07/06/2010**

### **General Changes**

- None

### **Defect fixes**

- CSET 143487(CQ 142911) - IO's to the target mode LUNs stops on port reset to the Target mode controller - When the target mode driver is reset, the links will go down then up. The initiator will process events to block and unblock IO for the link status changes. Prior to unblocking IO, the driver will send a Test Unit Ready, followed by start unit if required. The response returned to initiator for TURs is MPI2\_SCSI\_STATE\_TERMINATED. Due to bug in initiator driver, the MPI2\_SCSI\_STATE\_TERMINATED is treated as a success. The driver will subsequently next ask for serial number which will fail, then the driver will remove the device, and add it back later. To fix this issue, the driver will need to solve the processing of the SCSI state and status so non-zero value is returned with DEVICE\_RETRY instead of DEVICE\_READY. When DEVICE\_RETRY is returned, the TURs will be retried several times. When SCSI state and status transitions back to good values, the serial number check will work, and the device will not be deleted
- CSET 143481 (CQ 136939) - Bad request seen after many hours in reset expander test: The firmware development reported that the driver was sending a SCSI\_IO with the device handle set to 0xFFFF. The driver would only set the device handle to 0xFFFF after having received the device deletion event. Though nearly impossible that IO would be sent to end device after having received a device deletion, there is two cases where a small window is open to this. (1) IO Sent to the normal IO queue command function: There is a sanity check for the 0xFFFF device handle at the top of function, and however it is possible that the device handle could change by the time MPI function was filled out with the device handle. (2) Internal generated SCSI\_IO: Typically this is only called when devices are added. Highly unlikely a device addition and device delete are going on simultaneously. However there is no check in the routine for a device handle 0xFFFF. The fix will address both cases to include a sanity check on device handle of 0xFFFF. It will be impossible that 0xFFFF device handle will ever be sent to firmware

## **Major Changes For Version 07.254.02.00-1**

**Release Date: 05/24/2010**

### **General Changes**

- CQ 141004 - remove support for MPI2\_EVENT\_TASK\_SET\_FULL: This event is obsoleted in Phase 7, so this processing of this event needs to be removed from the driver. The controller firmware is going to handle TASK\_SET\_FULL; the driver doesn't need to do anything. Even though we are removing the EVENT handling, the behavior has not changed

between driver versions because firmware will still be handling queue throttling, and retrying of commands when the target device queues are full.

- CQ 139813 - MPI2 Rev O (2.0.7) and v2.00.16 header files (for Phase 7.0)
- CQ 139811 - ability to override/set the ReportDeviceMissingDelay and IODeviceMissingDelay from driver: Add new command line option missing\_delay, this is an array, where the first element is the device missing delay, and the second element is io missing delay. The driver will program sas iounit page 1 with the new setting when the driver loads. This is programmed to the current and persistent configuration page so this takes immediately, as will be sticky across host reboots.
- CQ 139805 - create a pool of chain buffers, instead of dedicated per IO: This enhancement is to address memory allocation failure when asking for more than 2300 IOs per host. There is just not enough contiguous DMA physical memory to make one single allocation to hold both message frames and chain buffers when asking for more than 2300 request. In order to address this problem we will have to allocate memory for each chain buffer in a separate individual memory allocation, placing each chain element of 128 bytes onto a pool of available chains, which can be shared among all requests.

## **Defect fixes**

- CSET 139807(CQ 134854) - Fix panic in the driver interrupt handler routine when controller firmware returns an invalid system message id (smid). The oops is occurring because mpt\_callbacks pointer is referenced to either NULL or invalid virtual address. This is due to cb\_idx set incorrectly from routine \_base\_get\_cb\_idx. The cb\_idx was set incorrectly because there is no check to make sure smid is less than maximum anticipated smid. To fix this issue, we add a check in \_base\_get\_cb\_idx to make sure smid is not greater than ioc->hba\_queue\_depth. In addition, a similar check was added to make sure the reply address was less than the largest anticipated address. The underlying issue is in firmware bug. The firmware bug was eventually solved in phase 5, however it was suggested by a firmware engineer that the driver have these additional safety net.

## **Major Changes For Version 06.00.00.00-1**

**Release Date: 05/06/2010**

## **General Changes**

- CQ 137376– Updated version number to 06.00.00.00-1 to indicate this release is a GCA release.

## **Major Changes For Version 05.254.05.00–1**

**Release Date:** 05/03/2010

### **Defect fixes**

- CSET 136629(CQ 133558) - While running heavy IOs and abort tasks through IOCTL interface every 7 seconds on a random drive, I/O errors were seen on the drives and I/Os failed: The bug is in the driver is due to not clearing the per device tm\_busy flag following the Task Management request completion from the IOCTL path. When this flag is set, the IO queues are frozen. The reason the flag didn't get cleared is because the driver is referencing memory associated to the MPI request following the completion, when the memory had been reallocated for a new request. When the memory was reallocated, the driver didn't clear the flag because it was expecting a task management request, and the reallocated request was for SCSI\_IO. To fix the problem the driver needs to have a cached backup copy of the original request.

## **Major Changes For Version 05.254.04.00–1**

**Release Date:** 04/23/2010

### **General Changes**

- CQ 124059 -- Drive S/N check for SATA drives: Add support to obtain the serial number for all devices, it will be stored in the sas\_device object at detection time. The serial number is in INQUIRY VPD Page 0x80. Then the serial number will be requested again when links are coming back up after having been lost. If there is a serial number mismatch for matching SAS address, the driver will delete the old device, and then add the new.

### **Defect fixes**

- CSET 135091(CQ 131614) - Sense data buffer not available for SCSI IO passthrough responses: (1) driver was not setting the sense data size prior to sending SCSI\_IO, resulting in the 0x31190000 loginfo. (2) The driver needs to copy the sense data to local buffer prior to releasing the

request message frame. If not, the sense buffer gets overwritten by the next SCSI\_IO request.

- CSET 132889(CQ 132867) –When a user invoked HBA scan through the sysfs entry “/sys/class/scsi\_host/hostX/scan” the SML scans for devices up to the maximum number of channels supported by the LLD for the particular controller and in each channel the scan goes to the maximum number of targets supported. The mpt2sasbtm driver sets the max\_channel value to default (0) one channel and the max\_id (the maximum number of targets) to -1. This was done to allow the host to scan the maximum possible number of targets. Since the -1 equals to 4294967295(0xFFFFFFFF) in unsigned, the scan was continued until the target ID reaches it. So the user sees it as a console freeze. For all non configured targets the driver throws a warning saying the sas\_device=NULL, this print adds delay for scanning. This is fixed by setting the max\_id to a small number which is equivalent to the number of targets and volumes supported by a particular controller (retrieved from IOC facts) and by moving the message prints from default to debug only prints.

## **Major Changes For Version 05.254.03.00-1**

**Release Date: 04/06/2010**

### **General Changes**

- CSET 131401(CQ 131193) – Added support for internal TUR retries until the command retry count is exhausted while handling the Link status change link up events.
- CSET 131085(CQ 125138) - Add additional sas\_address/phy messages in driver.  
Adding additional messages to the error escalation callbacks which display the wwid, sas address, handle, phy number, enclosure logical id, and slot. In the same eh callbacks, routines, the printk were converted to sdev\_printks, which displays the bus target mapping. These additional modifications help better identify the device which is in recovery.

### **Defect fixes**

- CSET 131400(CQ 129932) - Incorrect checking of pci resource flag using PCI\_BASE\_ADDRESS\_SPACE\_IO  
On a customer specific PowerPC platform, the driver failed to load due to incorrect mapping of PCI Memory Resources. The driver fix is to add

additional sanity check to make sure the driver traverses pci resources which are IORESOURCE\_MEM prior to calling ioremap.

- CSET 131091(CQ 131059) - While sending IO to devices, an internal generated host reset results in driver returning DID\_NO\_CONNECT for all scsi commands.

**BUG DESCRIPTION:**

A change from CQ 129053 created this issue. We added support to set the deleted flag prior to device scan, then clear the flag for responding devices, leaving the deleted flag only set for missing devices. The problem is for internal generated host resets, IO queues are not blocked at scsi mid layer level. IO will be continued sent to driver, and driver will return SCSI\_MLQUEUE\_HOST\_BUSY. The problem is the driver checks for the deleted flag before it checks for the controller being in reset, so there is a small window that the driver would be returning DID\_NO\_CONNECT for responding devices.

**BUG FIX**

Fix the queuecommand entry point so ioc->shost\_recovery flag sanity check is given higher precedence then the device "deleted flag" check.

- CSET 131089(CQ 131060) - discovery kicks off after port enable returns  
Add support in driver so it will wait for discovery to complete before returning from the send\_port\_enable routine. There are some cases where firmware is doing discovery after port enable completes, when it does this, the driver will not have all the devices in the sas\_device\_init\_list list prior to calling the sort routine for reporting boot devices to OS.
- CSET 131083(CQ 125137) - Timeouts in mult-pathing environment in SLES11.

**BUG DESCRIPTION:**

Setup SAS drive with two cables connected to controller. Load the driver with the mpt2sas\_multipath command line option enabled. Start the device-mapper driver stack. Send IO to /dev/dm-1. After some time has elapsed, then issue target reset to /dev/dm-1 using the tool `sg\_reset -d /dev/dm-1`.

**Bug Fix:**

Add support in the function mpt2sas\_scsih\_check\_tm\_for\_multipath so the driver processes LOGICAL\_UNIT\_RESET. Currently it was only supporting TARGET\_RESET. So with this fix, the driver will be sending an ABRT\_TASK\_SET over to the other path, this will flush out all the command that were dropped to the floor due to either LOGICAL\_UNIT\_RESET or TARGET\_RESET.

- CSET 131081(CQ 130633) - Volume not deleted after host reset

**BUG DESCRIPTION:**

This test case involves creating two RAID1 volumes, and then simultaneously issue host reset and pull all the drives associated to the 1st raid volume. The observed behavior is the physical drives are removed, however the volume remains. The expected behavior is the volume as well as physical drives should be removed from OS.



#### BUG FIX:

Add support in the post host reset device scan logic for raid volumes where the driver will have an additional check for responding raid volume where the status should be either online or optimal, or degraded. So for volumes that have a status of missing or failed, the driver will mark them for deletion.

## **Major Changes For Version 05.254.02.00-1**

**Release Date:** 03/31/2010

### **Defect fixes**

- CSET 130576(CQ 125906) - Mpt2sas and blocked devices  
Bug Description:  
If error recovery is occurring at the same time when a device is blocked, the escalation will always escalate to host reset. The reason for escalating is due to TURs sent by scsi mid layer function scsi\_eh\_tur after each Task Management request. Those TURs are failing because the driver is returning SCSI\_MLQUEUE\_DEVICE\_BUSY from the queuecommand callback.  
Bug Fix:  
The change is for the driver to return DID\_OK for the TURs sent during error recovery while the device is blocked. From the scsi mid layer scsi\_unjam\_host function, when TURs succeed, the eh\_scsi\_cmd is going to be moved from eh\_work\_q to eh\_done\_q. At the end of error recovery, all the scsi\_cmnds on the eh\_done\_q, are put back on the request queue from the scsi\_eh\_flush\_done\_q function. Those commands are retried and sent to target (hopefully unblocked by that time). The point is there is no reason to escalate error recovery for blocked devices.
- CSET 130574(CQ 125307) (Red Hat Bugzilla 567965) - Add missing initialization: In the driver mpt2sas\_base\_attach subroutine, we need to add support to return the proper error code when there are memory allocation failures, e.g. returning -ENOMEM.
- CSET 130572(CQ 125321) (child activity to CQ 118104) - Add old behavior into driver for RAID configuration when removing devices: The new driver behavior will only send target reset to PD when there is a single drive pull from a volume. This change occurred in CQ 118104. The older driver would be sending target reset to volume when there was a single drive pull from volume. The fix in the CQ is to send target reset to volume when there is a single drive pull, wait for the reply, then send target resets to the PDs. We want to add this behavior back so the driver will behave the same for older versions of firmware.
- CSET 130141(CQ 129053) - Data corruption after drive-pull during diagnostic reset.

#### RECREATE:

This issue surrounds issuing a host reset to the controller then at the same time a single drive is removed. Following host reset, the driver will send a port enable to firmware which results in a rediscovery of all devices. Sometimes a rediscovery of devices can result in device handle assignments changing, especially when a single device is removed.

#### BUG DESCRIPTION:

The bug is the device driver is scanning for devices after host reset processing completes. Since we are refreshing the handles after reset, there is a window where IO could be going to the old device handle.

#### BUG FIX:

- (1) The driver will be scanning for devices before the host processing completes, and appropriately setting device handles to their new assignments. The three functions `_scsih_mark_responding_xxx` have been moved from the hot-plug work task to host reset context.
- (2) A new function was added to set all devices to the deleted state, then clear the flag during the device scan for responding devices. At conclusion of the device scan, only missing devices will be left with the deleted flag set. With the deleted flag set, the driver will return `DID_NO_CONNECT` for all scsi commands during such time the hot-plug work task was activated to report all missing devices to the scsi mid layer.

## **Major Changes For Version 05.254.01.00-1**

**Release Date:** 02/22/2010

### **General Changes**

- CQ 124294 – Add support to display additional debug info for SCSI\_IO and RAID\_SCSI\_IO\_PASSTHROUGH sent from the normal entry queued entry point, as well as internal generated commands, and IOCTLS. The additional debug info included the phy number, as well as the sas address, enclosure logical id, and slot number. This debug info has to be enabled thru the `logging_level` command line option; by default this will not be displayed.
- CQ 124086 – The changes suggested by the external code review are implemented
- CQ 124085 – The driver is modified to use default descriptor instead of scsiio descriptor while sending RAID passthru commands, this is as per latest MPI spec. This is a Must requirement for RAID passthru to work with FW versions later than 05.00.00.00
- CQ 124078 – The driver is modified to detect a drive which returns sense data 04/19/01 (sense/asc/ascq) during the hotplug time,

- CQ 124071 – Added three new shost attributes: `host_trace_buffer`, `host_trace_buffer_enable`, and `host_trace_buffer_size` for registering and retrieving firmware trace buffer through the sysfs interface.  
 The `host_trace_buffer_enable` attribute is used to either post or release the trace buffers.  
 The `host_trace_buffer_size` attribute contains the size of the trace buffer.  
 The `host_trace_buffer` attribute contains a maximum 4KB window of the buffer.  
 In order to read the entire host buffer, the offset has to be written to `host_trace_buffer` prior to reading it. There is a script provided into the source code kit which will release the host buffer, then write the entire host buffer contents to a file.
- CQ 124065 – In OS distributions KERN\_DEBUG logging turned off by default and it is painful to configure systems so they receive KERN\_DEBUG messages when debugging issues. Many times when looking at logs, most critical information is missing. So all the KERN\_DEBUG messages are converted to KERN\_INFO.
- CQ 124063 – MPI headers updated to revision N
- CQ 124061 – A new sysfs attribute `ioc_reset_count` is added, which can be retrieved by reading the `/sys/class/scsi_host/hostX/ioc_reset_count`. This will provide the number of hard and soft reset issued by the driver.
- CQ 124058 – Added support to disable topology discovery during driver load time, a new module parameter `disable_discovery` is added and if it is set 1 during driver load time then the driver will not issue port enable call to the firmware and hence will not kick off the discovery. At a later point in time user can start the discovery by issuing host reset either through sysfs or ioctl interface

## **Defect fixes**

- CSET 124356(CQ 119210) – Kernel panic during early boot: The panic is in `_scsih_sas_device_remove` when the driver was attempting to delete an object from the `sas_device` link list when the object was not present. This is fixed by adding a check to verify whether the object is present in the list before deleting it from the list.
- CSET 124089(CQ 118104) - HBA firmware fault 600F: The fault is a result of the driver receiving the top level expander removal event prior to all the individual PD removal events; hence the driver is breaking down all the PDs in advanced to the actual PD UNHIDE event. In addition. The fault is a result of the driver sending multiple Target Resets to the same volume handle for each individual PD removal.  
 To fix this issue, the entire PD device handshake protocol has to be moved to interrupt context so the breakdown occurs immediately after the

actual UNHIDE event arrives. The driver will only issue one Target Reset to the volume handle, occurring after the FAILED or MISSING volume status event arrives from interrupt context. For the PD UNHIDE event, the driver will issue target resets to the PD handles, followed by OP\_REMOVE. The driver will set the "deleted" flag during interrupt context.

- CSET 124068(CQ 114298) - Node crashed by performing device resets in parallel with bus/host resets: The driver had an oops is because a host reset was sent by SCSI mid layer while there was already an host reset active, either issued via IOCTL interface or internally, like a configuration page timeout. Since there was a host reset active, the driver would return a FAILED response to the SML. Then the SML would begin cleaning up all the pending SCSI commands memory blobs before the driver called scsih\_flush\_running\_cmds, hence the SCSI command request\_buffer would be set to NULL. Then when the driver called pci\_unmap\_sg, the scsi cmd request\_buffer was NULL, and we oops. The solution is make sure pending host resets will wait for the active host reset to complete before returning control back up the call stack.

## **Major Changes For Version 05.00.00.00-1**

**Release Date:** 02/09/2010

### **General Changes**

- CQ 120990- Updated version number to 05.00.00.00-1 to indicate this release is a GCA release.

## **Major Changes For Version 04.254.05.00-1**

**Release Date:** 01/25/2010

### **General Changes**

- CQ 118212 - Updated copyright to year 2010.

### **Defect fixes**

- CSET 119658(CQ 119225) - \_scsih\_determine\_disposition - in switch, missing break for MPI2\_IOCSTATUS\_SCSI\_IOC\_TERMINATED: The driver is missing a break inside the switch/case for ioc\_status. Since the break is missing, the function is returning the incorrect disposition DEVICE\_READY for the case when TURs are sent during cable pull. Also

added support in the same function so devices returning sense key NOT\_READY, with ASC=0x3E, meaning device is self configuration, so the START\_UNIT is sent later from the calling function.

- CSET 118213(CQ 117637) - Bug fix in the handling of the internal device reset event: The reason code check in `scsih_sas_device_status_change_event` never evaluates as true for internal device reset, hence driver never quiesce IO when firmware is sending a device reset. This is fixed by modifying the logical expression to evaluate properly.
- CSET 117577(CQ 114786) - Fix NULL pointer dereference in `mpt2sas_base_hard_reset_handler`: The completion "`ioc->shost_recovery_done`" was not initialized prior to calling `complete()` near the end of the function call. Typically it would of been initialized from the hotplug work task function `_mpt2sas_fw_work`, however in this particular test case, the hard reset function completed to the end of the function before the work task got \activated, hence the null pointer dereference. To fix this issue, we need to initialize "`ioc->shost_recovery_done`" at driver load time.
- CSET 117576 (CQ 113732) - setting queue depth for meteor: The driver failed to load due to a very large memory allocation failure when creating the `ioc->scsi_lookup`. To fix this issue, we need to use the `get_free_pages` API. Also, the `ioc->chain_depth` need to be changed from a 16bit to 32bit variable because the number of chains will exceed 64k when the queue depth is large.
- CSET 117573(CQ 114752) - Linux driver fault 1500: The fault 1500 is a result of the driver sending command to firmware during message unit reset. This issue is reproduced by rebooting the system, then at the same time pulling cable to an enclosure full of drives. The problem was due to hot-plug work threads being still active when the shutdown routine was called. To fix this problem the driver will set the flag "`ioc->remove_host`" from the shutdown routine, then also break down the hot-plug work threads, and any pending work. Also added were several sanity check for the flag "`ioc->remove_host`".

## **Major Changes For Version 04.254.04.00-1**

**Release Date:** 12/21/2009

### **Defect fixes**

- CQ 114381 – Direct attached drives are not shown if the controller is configured in enclosure slot mapping: The previous version of the driver was modified to check for zero NumSlots, Due to coding error, the zero check is implemented as non-zero check and resulted in not adding a valid enclosure. This is fixed in this release.

## **Major Changes For Version 04.254.03.00-1**

**Release Date:** 12/18/2009

### **Defect fixes**

- CSET 114233(CQ 106189) – Bus/target mapping in enclosure/slot mode and with a multi-path configuration was becoming corrupted because the mapping table only had the enclosure logical ID and did not have the PhyBits information. With multi-pathing, an enclosure instance is the combination of the enclosure logical ID and the PhyBits field (which PHYs are used to connect to the enclosure). The fix was to add a PhyBits field to each Mapping Table entry and modify the mapping code to check both the enclosure logical ID and the PhyBits when trying to match an enclosure add event to possible existing entries in the mapping table. Code was added in each routine that adds mapping table entries to also add the PhyBits. Also, added a check when processing an enclosure add event for NumSlots equal to 0. This should never happen since the enclosure should at least have an SES device and it needs at least one slot in the enclosure so the SES device can be mapped. If NumSlots = 0 then the driver does not add the enclosure to the enclosure table and a error message will be logged.
- CSET 113899(CQ 113882) – The timestamp is wrongly calculated in 32bit OS due to improper type casting. That is fixed in this release
- CSET 113897(CQ 113305) - hotplug/diag reset: This CQ created to clean up code related to test cases where devices are added or removed while diagnostic reset is active. There is one bug fix which was created when solving another issue; CQ 107285. Basically this bug fix surrounds the problem where devices are not being removed from the operating system when diagnostic reset is sent. In addition to this fix, we have enhanced the algorithm surrounding the scanning and deletion of missing devices following host reset. What we did is moved this code to the hotplug work threads from diag reset context and watchdog timer. The purpose of moving this code is to prevent race condition when driver was deleting and adding the same device at the same time. During this race, it is possible to hit an oops in the sas transport layer when phys are attached to two separate ports at the same time.
- CSET 113896(CQ 107271) – When a drive with write cache enabled is removed then the driver stops further processing of events like device deletions or insertions. The system needs reboot to recover. This had happened due to the code change to fix the issue CSET 103586 in the 4.00.01.00 driver. The driver code is modified to unblock the device before removing the device. This enables the synchronize cache command to be processed and avoids the deadlock and allows further processing of the events.

- CSET 113894(CQ 112841) - sata devices not discovered: A change in previous CQ 110388 changed this behavior. This change caused sata devices with access flags bits set to SATA\_NEEDS\_INITIALIZATION to fail. Actually this is not a failure since sata devices will return this bit set prior to the first a scsi command sent. So to fix this, the driver will not treat NEEDS\_INIT as failure. In addition to this fix, the driver will now display message to describe the the access flags when bits are set, so the end user can better understand failures.

## **Major Changes For Version 04.254.02.00-1**

**Release Date:** 11/26/2009

### **General Changes**

- CSET 111075(CQ 110388) - too many report luns/turs: The report\_luns/tur logic is in the driver used to check responsiveness of devices prior to reporting to scsi mid layer, and/or unblocking. Apparently the driver currently is sending too many turs unnecessarily and redundantly. This driver patch cleans up the code so report luns is only issued when device are first reported; then report\_luns will be skipped since the lun number is available. Following host reset, we will only send turs/spin\_ups for devices in blocking state; e.g. its not required to send turs for devices that were already responding prior to the reset. Also for wide ports, we will only send turs for one phy, instead of every phy. Another fix is to refresh the device handles following phy link status change.

### **Defect fixes**

- CSET 111081(CQ 104522) - host reset hangs when pulling a drive while running IO stress test: The design of the driver is to remove non-responding devices following host reset. When devices are removed, the scsi mid layer will send SYNC\_CACHE scsi passthru if WCE is enabled. This can't be done during host reset because the scsi mid layer puts controller into SHOST\_RECOVERY state, which freezes all IO to devices, hence deadlock occurs. The fix this problem, we need process device removals outside the host reset context. This code was moved to the watchdog subroutine.
- CSET 111079(CQ 110306) - ppc64 sas2flash failure investigation: On ppc64, a 32bit application was failing due to data buffers not being copied properly from user to kernel memory. The problem due to improper

conversion of 32 to 64 bit pointers. The fix is to use `compat_ptr` to setup the pointer compatibility in the routine `ctl_compat_mpt_command`.

- CSET 111077(CQ 107285) - external host not connecting after controller reboot: The reported problem is: devices are not coming back after having the cable disconnected then reconnected. The problem is because the driver/firmware device removal handshake is failing. Due to this failure, the controller firmware is not sending out device add events when the target is reconnected. This is root caused to a race in the driver/firmware device removal algorithm. There is duplicate code in both interrupt and user context; where target reset is being issue from user context path while `sas_iounit_control(OP_REMOVE)` is being sent from interrupt context. An active `target_reset` will fail the `OP_REMOVE`. To fix this problem, the duplicate code has been removed from user context path.

## **Major Changes For Version 04.254.01.00-1**

**Release Date:** 11/06/2009

### **General Changes**

- CSET 106328(CQ 106191) – MPI Headers updated to version 02.00.14.
- CSET 103636(CQ 103188) – Added RHEL4.7 back into the dkms prebuilt binaries in addition to the existing rhel4.8 binaries.
- CSET 102609(CQ 098428) – Add new command line parameter `sdev_queue_depth`. This will globally set the queue depth for all SAS devices at once (ignoring SATA and volumes). This parameter can be set at driver load time.

### **Defect fixes**

- CSET 107179(CQ 107107) – Use `resource_size_t` to define the type resource for the system interface register set. The existing implementation was using "unsigned long" which would be 32 bit in 32 bit OS. A customer reported that his 32 bit OS is using 64 bit physical address space for the system interface register set, therefore we need to shift to using `resource_size_t` which takes care of physical address space.
- CSET 107177(CQ 104563) – Endian fixes.
- CSET 106127(CQ 105334) – The driver logs error indicating the enclosure can not be removed as it is already removed if one of the path of multipath capable enclosure is connected and removed: On removal of an enclosure the PhyBits reported in the SAS Enclosure Status Change event are set to 0. The driver was using the Logical ID and PhyBits to locate the enclosure in the driver enclosure table. This would not find a match due to the 0 PhyBits. Changed the enclosure removal handler function to use the



enclosure handle to find the entry on a removal instead of the combination of Logical ID and PhyBits.

- CSET 103607(CQ 102692) – When the dkms rpm is installed, it updates the driver properly in the /lib/modules and it recreated initrd image. But the resulting initrd image does not contain the mpt2sasbtm driver due to the reason that dkms rpm does not add an entry for mpt2sasbtm in /etc/modprobe.conf. Hence if the OS is installed using the DUD created using dkms, after installation while doing the reboot the drivers are not getting loaded and resulted in panic. To fix this the "MODULES\_CONF\_ALIAS\_TYPE[0] = "scsi\_hostadapter" " line is added in dkms.conf file to let the dkms add an entry in the modprobe.conf. This makes the mkinitrd to add the driver in the initrd image.
- CSET 103588(CQ 102810) – system halts during jammer scripts and medusa stress: There is a kernel oops when a host reset is called while the driver hotplug work threads are active. This oops root caused to the routine \_scsih\_remove\_device. This function was re-entered while in the process of deleting a device from work task context, then at the same time from host reset context when invoking a topology rescan. Since the routine was active at the same time from two different contexts, a panic resulted due to sas\_device deleted twice from the link list ioc->sas\_device\_list. The fix for this race condition is to immediately remove the sas\_device from the link list at the top of the function. An additional fix was added to make sure all pending work was canceled across diag\_reset; the fix was to add the cancel\_pending\_work flag from the fw\_event\_work structure, and then to set the flag during host reset, check the flag later from work threads context.
- CQ 102488 – When expanders are connected in topology a kern error "failure at mpt2sas\_scsih.c:5331/\_scsih\_add\_device ()!" is logged: The link status change event handling, mistakenly tried to add expanders in the topology as end device hence the failure is reported. Fixed by adding proper break statement in switch case of link status change handling.
- CSET 102476(CQ 101922) – ioctl returns success on timeouts: The driver was modified to return -ENODATA when there is a timeout via ioctl path.

## **Major Changes For Version 04.00.00.00-1**

**Release Date:** 10/12/2009

## **General Changes**

- CQ 102472– Updated version number to 04.00.00.00-1 to indicate this release is a GCA release.

## **Major Changes For Version 03.254.04.00-1**

**Release Date:** 09/24/2009

### **General Changes**

- CSET 99576(CQ 99447) – Add support for F/W multi-pathing: Host mapping code was modified to look at the PhyBits field in the SAS Enclosure Status Change event. The Phybits indicate which phys are being used for this enclosure. The PhyBits are maintained in the local driver enclosure table as well as in the DPM Page 0 persistency page entries. The use of the PhyBits allows the driver to determine the multi-pathing capabilities when dual ported devices reside in the same Enclosure Logical ID (attached to two different expanders).
- CSET 95346(CQ 64808) – Added 'fixid' rpms.

### **Defect fixes**

- CQ 99232 – Linux Driver-SAS Volume mapping failure while creating RAID volumes in PPC systems. The endianness conversion was missed in couple of places in mapping code which is causing the issue. This is fixed by addressing those conversions.
- CQ 99675 –Persistent SAS address creation for ATAPI device failed: When an ATAPI device is connected in the topology, it is not visible to the OS and the driver throws error indicating the SAS address creation failed: The driver is modified to issue Identify packet device command (0xA1) for ATAPI devices and Identify device (0xEC) for other devices. Also the SASStatus is checked for success of the command in addition to IOC status. In addition the driver is modified to use the SAS device Page 0 provided SAS address if the Hashed SAS address creation is failed. This change will allow the user to see the device even if the persistence SAS address creation is failed. But the IDs may not be persistent.
- CSET 99578(CQ 98589) – Snowmass - IO Stress and random TM causes STAF script to lock up: This was due to dead lock between the user issued task management and kernel error recovery handler issued task management. This is fixed by moving the task management mutex to the core function which issues task management.

## **Major Changes For Version 03.254.03.00-1**

**Release Date:** 09/09/2009

## **General Changes**

- CQ 95350 – Binary level support for PPC architecture is added
- CSET 97581(CQ 97308) - add a bad disk to the OS: Made an exception for medium errors of ASC=0x31. The test unit ready will allow the drive to continue on through the device add process.
- CSET 95625(CQ 95433) - making sysfs attribute task\_management more robust: (1) Add support to freeze the scsi host IO queue while sending these TM's; this replaces the code that was freezing each device queue individually. (2) Add "out of hi-priority request" message when there are no available message frames. (3) Add support for going to sleep when there are no available message frames, then waking up later when frames come available. This should allow all the task management request to be sent when there is a shortage of free request message frames. (4) Add support to exit early when controller goes into fault state. (5) Add spin locks in the target reset loop when traversing the sas\_device and raid\_device link list (6) Add statistics support with a message that displays the number of task management request sent and the number of IOs that were terminated. (7) Add message to display the smid in the task management request and completion. For task abort it will be the smid that is being aborted, instead of the task management smid.
- CSET 95621(CQ 95459) - mpt2sas\_fwfault\_debug - make this parameter set per controller instance: (1) created ioc->fwfault\_debug parameter - which is per controller (2) created new function \_scsih\_set\_fwfault\_debug, which will globally set each instance of ioc->fwfault\_debug (3) renamed the shost sysfs attribute from mpt2sas\_fwfault\_debug to fwfault\_debug (4) modify the sysfs callbacks to read and write the attribute fwfault\_debug individually for each controller instead of globally.
- CSET 95334 (CQ 94747) - add changes required by kernel.org: scsi\_internal\_device\_block - scsi lld should use the block/unblock common API for blocking devices instead of setting the sdev state directly. The devices also need to be unblocked prior to reporting it as missing or it will deadlock in the mid layer.
- CSET 93303 (CQ 90767) - Add Extended Type for Diagnostic Buffer Support: (1) Add extended buffer support in \_ctl\_diag\_capability so this function returns success when ioc facts capabilities says firmware supports EXTENDED. (2) Add a print to send the message "Diag Extended Buffer" string to system log when ioc facts capabilities says firmware support EXTENDED. (3) Add support in the command line option diag\_buffer\_enable to support EXTENDED buffers when bit 2 is set. (4) Update comments section of the source code to indicate the buffer\_type can be EXTENDED in addition to TRACE and SNAPSHOT.

## **Defect fixes**

- CQ 98244 – Kernel panic when the device\_rescan script is executed multiple times without enough time in between. Then the slave\_destory functions ends up accessing a NULL sas\_device pointer. This is fixed by checking for NULL before accessing the pointer.
- CQ 95345 – Fix SLES9 SP4 DUD. Modified the dud update.post script not to do chroot and also modified the makedud script to clean the previous built object files before making a new kernel build.
- CSET 97578(CQ 95191) - freeze the sdev IO queue when firmware sends internal device reset: When receiving the `MPI2_EVENT_SAS_DEV_STAT_RC_INTERNAL_DEVICE_RESET` event, the driver will set the `tm_busy` flag in the sdev private host data, when `tm_busy` flag is set, the driver will return `SCSI_MLQUEUE_DEVICE_BUSY`, effectively freezing the IO to the device. The `tm_busy` flag is cleared with the `MPI2_EVENT_SAS_DEV_STAT_RC_CMP_INTERNAL_DEV_RESET` event.
- CSET 97456(CQ 97420) - PPC (power pc) endian bug fix's: (1) EEDP(End to End data protection) was not working. This was due to not setting EEDP BlockSize and Flags to little endian format in the message frame. (2) Some expander sysfs attributes were not getting set properly. The sas format was not getting set due to endian issues with `sas_format` field in the struct `rep_manu_reply`. Since `sas_format` was not set properly, the `component_vendor_id`, `component_revision_id`, and `component_id` were not set. (3) In `_transport_smp_handler`: we don't need to convert the `smid` from little endian to cpu prior to calling `mpt2sas_base_free_smid`, because its already in cpu format. (4) Some loginfos and ioc status were not converted from little endian to cpu.
- CSET 96917 (CQ 96109) - `mpt2sas_base_get_sense_buffer_dma` should be returning little endian: From the function `mpt2sas_base_get_sense_buffer_dma` add support to call `cpu_to_le32` when calculating the physical dma address. This will properly handle endianness on big endian systems. The return value of this function was changed from `dma_addr_t` to `__le32`. Remove the typecasting of `u32` when setting the `SenseBufferLowAddress`, since it is already in `__le32` format.
- CSET 95341(CQ 95500) - cable pull testing: Its observed that the OS was sending request to the driver after it had been put into blocking state, so the driver was modified to return `SCSI_MLQUEUE_DEVICE_BUSY`. The parameter `spin_up_drive` was renamed to `wait_for_device` in the function `_scsih_ublock_io_device`, to better classify the meaning of this field. It

really means that we need to wait for the device to be ready to accept scsi commands before we put it back into running state.

- CSET 95341(CQ 95190) - Put controller in ready state when rebooting: Add support in the shutdown callback handler to put the controller in controller in READY state. This support is now going to be in both the driver un-load and reboot context.
- CSET 95339(CQ 95188) - Driver is not sending MUR at driver load time when EVENT\_REPLAY capability bit is set The driver needs to retrieve the ioc facts prior to putting the controller into READY state. The current design is calling ioc facts after putting the controller into READY state, which means the driver is sending a diag reset instead of message unit reset because the capability information is not yet available.
- CSET 95337(CQ 94963) - Phase 4.0 Linux Driver Unknown status displayed in dmesg: (1) for the MPI2\_EVENT\_SAS\_TOPOLOGY\_CHANGE\_LIST event when the ExpStatus is set to zero, display "responding" instead of "unknown status". This actually fixed in CQ 94517 (2) for the MPI2\_EVENT\_IR\_OPERATION\_STATUS event, add support to print "background init" or "make data consistent" for debugging purposes. If the RAIDOperation is set to a value not defined, then then don't print anything (3) for the MPI2\_EVENT\_SAS\_DEVICE\_STATUS\_CHANGE event, add support to print "expander reduced functionality" and "expander reduced functionality complete", which are new events.
- CSET 95330(CQ 94826) -LSI SAS Driver Stop code during W2K3E SP2 R2 X86 OS Installation. This issue is found in Windows but applicable to Linux also. The adapter being used in this test had a full persistency table (due to a prior F/W issue). The full persistency table uncovered a driver bug where a Bad Index value (0xFFFF) was being used to index into the local copy of the persistency table, resulting in an invalid memory access and blue screen. A mapping table entry can have a Bad Index value if the persistency table is full and that entry cannot be added to the persistency table. The driver fix is to check for a Bad Index value and not attempt any operations on the persistency table for that entry.
- CSET 95220(CQ 94517) - add IR support for the sysfs attribute task\_management: The following changes were made in the contents of sysfs attribute task\_management (1) remove support for sending task aborts to IR volumes and hidden raid components (2) add support to send target reset to IR volumes (3) remove support for sending target resets to hidden raid components (4) remove support for sending lun reset and abort task set hidden raid components (5) remove support for sending abort task to hidden raid components (6) target resets are sending link change rate events with no link rate change -> thus said the driver was modified so when there is no link rate change, we don't need to call mpt2sas\_transport\_update\_links nor \_scsih\_ublock\_io\_device. (7) There were changes made in \_scsih\_sas\_topology\_change\_event\_debug to

change the debug strings so they are more clear. Also the link rate change information was added to display the new and previous link rate.

- CSET 94409(CQ 94401) - mpt2sas\_transport\_port\_add: could not find parent sas\_address: When direct attaching devices to controller populating every phy, the very last device fails being report with the error message "could not find parent sas\_address". This failure is due to bug in \_scsih\_get\_sas\_address. This function was expecting the first phy of the controller to be handle zero, which is incorrect. Its actually handle 1. So the full range of handles assigned to the controller is 1 thru max phy count. So the sanity check in \_scsih\_get\_sas\_address was correct to include the max number of phys.
- CSET 92740 (CQ 90217) - Time Stamp - needs to be set in IOC\_INIT: Add support to set the TimeStamp when sending ioc\_init. The driver will call do\_gettimeofday kernel API to obtain the seconds+microseconds, which is provided to controller firmware.
- CSET 92783(CQ 90438) - don't allow end user to set SATA queue depth above 32: Add sanity check in \_scsih\_change\_queue\_depth to limit the max\_depth to 32 for SATA devices. This is only for physical devices not part of a volume.

## **Major Changes For Version 03.254.01.00-1**

**Release Date: 08/10/2009**

### **General Changes**

- CQ 82978 - SLES9 SP4 binary level support is added for x86 and x86\_64 architectures
- CQ 82978 - Support for diskdump is added.
- CSET 66952 (CQ 37567)- Support for stopping driver when Firmware encounters fault. Added command line option mpt2sas\_fwfault\_debug. When end user writes a "1" to this parameter, this will enable support in the driver for debugging firmware timeout related issues.
- CSET 90009 (CQ 68144) - add option to automatically post DIAGNOSTIC trace and snapshot buffers when Linux driver loads: Added command line option diag\_buffer\_enable. When the command line option is set, the driver will automatically post DIAGNOSTIC buffers at driver load time.
- CSET 90006 (CQ 35970) - Create SYSFS SHOST attribute for sending task management request. Created a sysfs attribute called task\_management in /sys/class/scsi\_host/host#. By witting a number to this attribute, it will do various types of task management. This code will send overlapping task management request to every device or pending

task depending on the task type. This code was added to help debug firmware task management issues.

Here are the supported numbers:

- 1 = diag reset
- 2 = message unit reset
- 3 = abort task
- 4 = target reset
- 5 = lun reset
- 6 = abort task set

- CSET 90003 (CQ 14691) - Add support for RAID Action System Shutdown Initiated at OS Shutdown:
- CSET 90017 (CQ 89677) - Linux SAS2.0 - Adding Phase 4.0 MPI Headers - revision L
- CSET 90015 (CQ 89640) - SAS2208/Thunderbolt support: Add support for PCI Device ID's range {0x80 - 0x87}
- CSET 82973 (CQ 82588) - Add support for sending multiple task management request at the same time
- CSET 90032 (CQ 85974) - not all devices are being recognized while doing full cable pull testing This handles the case where driver receives an expander removal event while it is in the middle of processing an expander add event. The existing implementation will stop processing further device adds when a expander delete arrives on top of an expander add. Due to a sanity check in the driver, the devices there were not added, were never notified to firmware with the device removal handshake protocol. Since the driver didn't do the handshake, the controller never provide further add events. To fix this issue, the sanity check was removed so the driver will always do the device removal handshake protocol.

## **Defect fixes**

- CQ 68900 - In device persistence mapping mode with RHEL4/SLES9 driver if an SATA disk is moved between different PHY's then the Target ID are changing. The expected behavior is the ID should not be changed even if the device is moved to a different PHY. This is fixed by creating a unique ID for SATA devices if the mapping mode is device persistence mapping. The ID is generated based on the SerialNumber and ModelNumber of the SATA drive and that ID will be used as Identifier for SATA device mapping instead of the SAS address.
- CQ 90317 - Linux Driver mpt2sasbtm : The driver persistency mapping is not working for Volumes. If two volumes are created and the volume with ID0 is deleted then the expectation of the persistence mapping is, the volume with ID1 should be retained with ID1 and any newly created volume should be assigned with ID0. But the behavior observed is, the

old volume gets ID0 and the newly created volume gets ID1. The driver is modified to do proper sized memory copy for the DPM page read from NVRAM to fix this problem.

- CSET 90030 (CQ 85944) - Corruption caused by SAS Truncated CMD Frame: Added support in the driver to check for valid response info in the SCSI state, then check to see if the response code is `MPI2_SCSITASKMGMT_RSP_INVALID_FRAME`; when this condition occurs, the driver will return `DID_SOFT_ERROR`. A return code of `DID_SOFT_ERROR` will result in a retry at the SCSI-mid layer level. An additional change added to obtain the response code from the 1st byte of the response info instead of last.
- CSET 90021 (CQ 82440) Drives not mapped on enclosure add after reset sequence. The device driver was not handling updating device handles in all cases across diag resets. To fix this issue, the driver is converted to using sas address instead of handle as a lookup reference to the parent expander or sas\_host. Also, for both expanders and sas host, the phy handle will be one unique handle. In the sas host case, the phy handle can be different for every phy, so the change is to set the handle to the handle of the first phy; every phy will be one single sas address(phy 0) instead of a different sas address for every phy(previous implementation). So making one consistent sas address for all the direct attached ports to the sas host, will make it better user experience when using `udev /dev/disk/by-path` dev nodes.
- CSET 90019 (CQ 80574) - IOCTLs fail after a SCSI passthru request times out. The driver needs to call `init_completion` on a per request basis. At some point the `wait_for_completion_timeout` is not waiting for the timeout, instead returning immediately, thus going into diag reset. This fix will address all requests using the `wait_for_completion_timeout` API. The previous implementation was only calling `init_completion` at driver load time.
- CSET 90026 (CQ 82718) - Inconsistent behavior when pulling/reinserting during IO (1) add support to spin up drives that are pulled and reinserted before device removal; the driver will delay putting devices in `SDEV_RUNNING`, following `SDEV_BLOCK`, until the drives have been spun up. (2) the device detection algorithm for "hot add" is enhanced; to include improvements surrounding devices that timeout on the first scsi commands attempts.
- CSET 90023 (CQ 79906) - 0402 Fault running heavy IO in I/T switching environment following a `diag_reset`, a request to send an `ioc_init` is timing out. The timeout occurred within the `HANDSHAKE` logic while waiting on firmware to acknowledge that the driver had wrote to the doorbell register. This was root caused to a logic timeout in the firmware code. The proposed solution is for the driver to call the `udelay` instead of `msleep` API in function where its looping reading the interrupt status. In addition to this change, there were two additional cases where we deleted the clearing interrupt status outside handshake context.



- CSET 90028 (CQ 84350) - Inaccessible drives not removed after zone configuration Add support to process device removal events when the phy status is set to MPI2\_EVENT\_SAS\_TOPO\_PHYSTATUS\_VACANT.

## **Major Changes For Version 02.00.01.00-1**

**Release Date:** 06/29/2009

### **General Changes**

- None.

### **Defect fixes**

- CQ 83973 – Volume created runtime with any tools like SAS2IRCU is recognized only after reboot: When the firmware sends a IR configuration change event the driver will be doing a match of the existing map table with the WWID of all the volumes added/created to find out the free mapping slot for the newly created/added volume. Due to an erroneous indexing even the physical disks events are considered for matching (with WWID == 0) and hence there was no space in the mapping table for newly created volume. The indexing is fixed properly and additional checking is added to avoid all Non-Volume events.

## **Major Changes For Version 02.00.00.00-1**

**Release Date:** 06/18/2009

### **General Changes**

- CQ 81655 – Updated version number to 02.00.00.00-1 to indicate this release is a GCA release.

### **Defect fixes**

- None.

## **Major Changes For Version 01.254.05.00-1**

**Release Date:** 06/11/2009

## **General Changes**

- CQ 81638 – Removed the Target Mode Driver Sources from the source tarball

## **Defect fixes**

- CSET 82303 (CQ 81462) – Ported the fixes done in mpt2sas driver for proper power management support.

## **Major Changes For Version 01.254.03.00-1**

**Release Date: 05/19/2009**

## **General Changes**

- CQ 78716 - Support for RHEL4 Update 8 is added. The RPM contains modules for 2.6.9-89 kernel. The dkms prebuilt binaries are replaced with the 2.6.9-89 kernel based binaries.
- CQ 75566 - A new proc entry /proc/mpt2sasbtm/version is added to provide the driver version.

## **Defect fixes**

- CQ 78884 - The dkms spec file has wrong kernel names for smp, largesmp and hugemem flavors and hence the dkms binary based installation will not install the .ko files for smp, bigsmp and hugemem kernels. Modified the kernel names in spec file to have proper flavors.
- CQ 75583 – Deleting volumes and multiple reboots causes panic. While updating the missing count for IR volumes the driver didn't consider the reserved ID (ID 0) in loop count and hence when two volumes are missing the missing count is updated for three entries in map table and the third entry in the map table is the disk present in the first slot of enclosure. The missing count will get incremented for every boot and hence after every boot the DPM is getting added with same map table entry. Because of this after 10 reboots (max enclosures is 10) the driver panics. This is fixed by updating the volume missing count update loop to start from actual volume mapping start index instead of 0.
- CSET 76186 (CQ 75657) - IR volumes deleted and re-created outside the OS do not get mapped on first boot: Fix for IR volumes: Whenever adding an IR volume and there is no space available in the mapping table, look at

all subsequent Volume Add entries in the IR event list and see if any match the Volume ID of the first IR mapping entry. If not, reuse that entry. If so, move to the next available IR mapping entry and repeat the Volume ID check. Fix for bare targets: At start-of-day, if any of the target additions cannot be mapped due to no space available, set a flag that a device add failed. After all initial mapping events have been processed, do the start-of-day checks (to see the missing counts), force a write of all changed DPM Page 0 entries, do a MUR or diag reset (MUR if events can be replayed), then retry the controller initialization (one more time). This allows the driver to determine what devices that were specified in the persistent mapping data are now missing, so those mapping entries can be reused for newly added devices.

- CSET 78707 (CQ 71559) - Target Driver is aborting an IO it shouldn't in I/T Switching Mode: The FW sends a reply frame for a task assist, and then almost immediately reuses the same io index for another SSP\_IU request. With the reply message frame just arriving for the previous TA, the driver kernel thread never went to sleep due to the new request. Apparently the kernel code didn't clean up the wait queue for previous command due to the nearly overlapping commands. So when the new request arrives, there is no 5 second wait, and the driver is immediately aborting the command. To fix the issue, the driver will need to call `init_completion()` prior to every target assist.
- CSET 78708 (CQ 74873) – Target Driver Data corruption during heavy copy/compare stress test: The issue occurs when memory is being allocated for the lun ramdisk. There is a race between reads/writes to the same sector when `dma_alloc_coherent` called and when memory is available. To fix this, the driver will return `SAM_STAT_BUSY` prior to calling `dma_alloc_coherent`. From the initiator, when `BUSY` is returned, it will retry the command, by that time the memory will be available.
- CSET 78709 (CQ 75081): (1) add support to retry `READ_CAPACITY16` when there is a unit attention.
- CSET 78710 (CQ 75352) - Power cycling cascaded expanders causes kernel panic: Code cleanup of the host reset handling of the driver, and fix hot plug work thread deadlocks, and kernel panics. (1) removed `ioc->ioc_reset_in_progress` flag, replaced with `ioc->shost_recovery`. (2) removed the spin lock around reading `ioc->shost_recovery`. (3) removed changing shost state during host reset handling; such as `SHOST_RECOVERY` (4) moved rescanning the devices, updating handles, and deleting not responding devices to the same contents at the host reset handling. (5) return `SCSI_MLQUEUE_DEVICE_BUSY` from `_qcmd` when `sas_target_priv_data->tm_busy` is set (6) set `SDEV_RUNNING` from contents of the interrupt, instead of work threads
- CSET 78711 (CQ 76322) - RAID10 volume creation is showing as RAID 1E - Add support to obtain manufacturing page 10 at driver load time. The driver will display RAID10 string when the volume type is RAID1E, when

there is a even drive count, and the manufacturing page 10 GenericFlags0 field has bit 2 is set.

- CSET 78712 (CQ 75917)- added sanity checks on volume add and removal to ignore events for foreign volumes.
- CSET 78713 (CQ 78035) - TLR Support - query vpd page 0x90: The driver is sending vpd page 0, to get a list of supported pages. Then it will traverse the list searching for page 0x90. When page 0x90 is present, the driver will enable the TLR logic for Tape devices only. The TLR logic will enable the TLR bits in the SCSI\_IO for every request. If there is a response with MPI2\_SCSITASKMGMT\_RSP\_INVALID\_FRAME, the driver will turn off the TLR logic.
- CSET 78714 (CQ 76771) - sas iounit config page0 timeout: 1) inhibit 0x3117 loginfos - during cable pull, there are too many printks going to the syslog, this is have impact on how fast the interrupt routine can handle keeping up with command completions; this was the root cause to the config pages timeouts 2) clean up interrupt routine to be more efficient. 3) clean up config page API - moving the setting and clearing of the mutex's to \_config\_request. There was a mutex deadlock when diag reset is called from inside \_config\_request, so diag reset was moved to outside the mutexs. Also deleted redundant code thru out the API, moving to common area; this reducing the code size by 1/3.

## **Major Changes For Version 01.254.02.00-1**

**Release Date: 04/15/2009**

### **General Changes**

- This driver is functionally equivalent to the mpt2sas driver version 01.255.02.00-1 (driver for RHEL5/SLES10/SLES11) without the following major features included.
  - Linux SAS transport layer
  - Access to hidden physical disks in IR volumes
  - MSI-X based interrupt handling support
  - Kernel specific features like Linux EEDP API support

## **Major Changes For Version 00.254.12.00-1**

**Release Date: 03/23/2009**

### **General Changes**

- Initial release.
- This driver is functionally equivalent to the mpt2sas driver version 00.255.12.00-1 (driver for RHEL5/SLES10/SLES11) without the following major features included.
  - Linux SAS transport layer
  - Access to hidden physical disks in IR volumes
  - MSI-X based interrupt handling support
- Implemented Host Mapping (Bus/Target ID mapping to device handle) at the driver level.