



## SCS Engineering Release Notice

---

*Phase17 GCA Release Version 17.00.00.00 - SAS2FLASH\_Phase17.0 (SCGCQ00468805)*

*(SCGCQ00468805) - Phase17 GCA Release Version 17.00.00.00 - SAS2FLASH Phase17.0*

*(SCGCQ00466023) - Phase17 Beta Release Version 16.250.04.00 - SAS2FLASH Phase17.0*

*(SCGCQ00451800) - Phase17 Beta Release Version 16.250.03.00 - SAS2FLASH Phase17.0*

*(SCGCQ00436762) - Phase17 Alpha Release Version 16.250.02.00 - SAS2FLASH Phase17.0*

*(SCGCQ00421174) - Phase17 Pre-Alpha Release Version 16.250.01.00 -*

*SAS2FLASH Phase17.0*



## SCS Engineering Release Notice

---

*Phase17 GCA Release Version 17.00.00.00 - SAS2FLASH\_Phase17.0 (SCGCQ00468805)*

***Defects=0, Enhancements=0 (Version Change Only)***



## SCS Engineering Release Notice

---

*Phase17 Beta Release Version 16.250.04.00 - SAS2FLASH\_Phase17.0 (SCGCQ00466023)*

### **Change Summary ( Defects=1)**

SCGCQ00463033 (DFCT) - SAS2FLASH:Version of SAS2FLASH displayed wrongly in ESX 5.1 U1 platform.



## SCS Engineering Release Notice

---

Phase17 Beta Release Version 16.250.04.00 - SAS2FLASH\_Phase17.0 (SCGCQ00466023)

---

### **Total Defects Resolved (1)**

(SCGCQ00463033)		Defect 1/1
<b>HEADLINE:</b>	SAS2FLASH:Version of SAS2FLASH displayed wrongly in ESX 5.1 U1 platform.	
<b>DESC OF CHANGE:</b>	Fixed while building the latest binary.	
<b>TO REPRODUCE:</b>	<ol style="list-style-type: none"><li>1. Uninstall the previous version of SAS2FLASH.</li><li>2. Install SAS2FLASH beta version (16.250.03.00)</li></ol>	
	Actual Result: The incorrect version 16.250.01.00(pre-alpha) is getting updated.	
	Expected Result: The correct version 16.250.03.00(beta) is to be updated.	
<b>ISSUE DESC:</b>	SAS2FLASH:Version of SAS2FLASH displayed wrongly in ESX 5.1 U1 platform.	

---



## SCS Engineering Release Notice

---

*Phase17 Beta Release Version 16.250.03.00 - SAS2FLASH\_Phase17.0 (SCGCQ00451800)*

***Defects=0, Enhancements=0 (Version Change Only)***



## SCS Engineering Release Notice

---

*Phase17 Alpha Release Version 16.250.02.00 - SAS2FLASH\_Phase17.0 (SCGCQ00436762)*

### **Change Summary ( Enhancements=1)**

SCGCQ00368532 (ENHREQ) - SAS2FLASH : CLI switch adder to force an update of the SBR from ManPage2 only and do not reset.



# SCS Engineering Release Notice

---

*Phase17 Alpha Release Version 16.250.02.00 - SAS2FLASH\_Phase17.0 (SCGCQ00436762)*

---

## ***Total Enhancements Implemented (1)***

<b>(SCGCQ00368532)</b>		<i>Enhancement 1/1</i>
<b>HEADLINE:</b>	SAS2FLASH : CLI switch adder to force an update of the SBR from ManPage2 only and do not reset.	
<b>NEW FUNCTIONALITY:</b>	Added new command -sbr that will update the SBR from ManPage2 if there is mismatch between SBR and ManPage2 values.	

---



## SCS Engineering Release Notice

---

*Phase17 Pre-Alpha Release Version 16.250.01.00 - SAS2FLASH\_Phase17.0 (SCGCQ00421174)*

### **Change Summary ( Enhancements=3)**

*SCGCQ00402918 (ENHREQ) - Phase 17 - RHEL 6.4 Support*

*SCGCQ00411893 (ENHREQ) - Phase 17 Oracle Linux 6.4 support*

*SCGCQ00415338 (ENHREQ) - Phase 17 Oracle Linux 5.9 Support*





## SCS Engineering Release Notice

Phase17 Pre-Alpha Release Version 16.250.01.00 - SAS2FLASH\_Phase17.0 (SCGCQ00421174)

### *Total Enhancements Implemented (3)*

(SCGCQ00402918)	Enhancement 1/3
-----------------	-----------------

**HEADLINE:** Phase 17 - RHEL 6.4 Support

**NEW FUNCTIONALITY:** Validation of SASFLASH on RHEL 6.4.

(SCGCQ00411893)	Enhancement 2/3
-----------------	-----------------

**HEADLINE:** Phase 17 Oracle Linux 6.4 support

**NEW FUNCTIONALITY:** Validation of SASFLASH on Oracle Linux 6.4.

(SCGCQ00415338)	Enhancement 3/3
-----------------	-----------------

**HEADLINE:** Phase 17 Oracle Linux 5.9 Support

**NEW FUNCTIONALITY:** Validation of SASFLASH on Oracle Linux 5.9.